



20240610 – BL000B – MULTI-BUILDING – BL107, BL405 – Replace Humidifiers
Addendum 3

November 6, 2025

General Notifications

Modifications described herein shall be incorporated into the project documents. All other work described in the project documents shall remain unchanged.

Acknowledge receipt of this Addendum by noting it on the Bid Form. Failure to do so may subject bidder to disqualification. This Addendum is a part of the contract documents.

Changes to Specifications

Section 237313 – SEMI-CUSTOM AIR HANDLING UNITS

1. Revise Article 2.02, Paragraph A.2.a to read: “Minimum 20-gauge galvanized steel outer panel with corrosion resistant coating.”
2. At Article 2.02, Paragraph C.4, revise the overhang to a minimum of ½”.
3. At Article 2.02, Paragraph C.5, revise the last sentence to read: “Drip edge guard to extend a minimum of ½” beyond door surface.
4. At Article 2.02, Add paragraph 12 to read: “12. Exterior Finish: Provide prime and final coat of the unit exterior with finish coating that when subjected to ASTM B117 3, 500-hour, 5% salt spray conditions, equivalent to an ASTM D1654 rating of ‘6’.

Attachments - None

End of ADDENDUM 3